



3 1/4" ALUMINUM CAP STAMPED
 LINN CO. SURVEYOR, T115 R3W,
 SE COR D.C. 38, LS 1907; 2002
 REMON BK. 18, PG. 89
 DESTROYED BY CONSTRUCTION.
 TO BE POST MONUMENTED AFTER
 IMPROVEMENTS IN THIS SURVEY,
 SEE SURVEY NUMBER 24122,
 LINN COUNTY SURVEY RECORDS.

PARCEL 1
 OF PARTITION PLAT NO. 2004-43

UM CAP
 Y GPS POINT
 NORTHWEST
 39)

W/Y/P